



RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Enid Public Schools - Adams Elementary School on February 23, 2024. Overall, nineteen (19) outlets were tested resulting in a total of thirty-eight (38) samples being sent to the lab.

- Thirty-three (33) samples had no detectable level of lead.
- Five (5) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-HALL-WC1	Elkay water cooler; near Room 32; left side	<1.0	<1.0	N/A
1-1-HALL-WC2	Elkay water cooler; near Room 32; right side	<1.0	<1.0	N/A
1-1-HALL-WC3	Oasis bottle filler; near Room 32	<1.0	<1.0	N/A
1-B-27-KF	Kitchen faucet in Teacher's lounge (Room 27); in basement	<1.0	<1.0	N/A
1-B-27-DW	Culligan drinking water spigot in teachers' lounge (Room 27); in basement	<1.0	<1.0	N/A
1-B-HALL-WC1	Oasis water cooler in basement hall	<1.0	<1.0	N/A
1-1-HALL-WC4	Elkay water cooler; left side; near Room 131; first floor	<1.0	<1.0	N/A
1-1-HALL-WC5	Elkay water cooler; right side; near Room 131; first floor	<1.0	<1.0	N/A
1-1-HALL-WC6	Elkay bottle filler; near Room 131; first floor	<1.0	<1.0	N/A
1-1-HALL-WC7	Elkay water cooler; near girls' restroom; first floor	<1.0	<1.0	N/A
1-1-HALL-WC8	Elkay bottle filler; near girls' restroom; first floor	<1.0	<1.0	N/A
1-2-HALL-WC1	Elkay water cooler; near boys' restroom; second floor	<1.0	<1.0	N/A

Sample ID	Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
1-2-HALL-WC2	Oasis bottle filler; near boys restroom; second floor	<1.0	<1.0	N/A
1-2-HALL-WC3	Elkay water cooler; left side; near restrooms and Room 231 on second floor	<1.0	<1.0	N/A
1-2-HALL-WC4	Elkay water cooler; right side; near restrooms and Room 231 on second floor	<1.0	<1.0	N/A
1-2-HALL-WC5	Elkay bottle filler; near restrooms and Room 231 on second floor	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 µg/L)				
1-1-KIT-KF2	Kitchen faucet in kitchen; right side	<1.0	2.4	
1-1-KIT-KF1	Kitchen faucet in kitchen; left side	3.0	4.6	
1-B-HALL-WC2	Oasis bottle filler in basement hall	4.0	1.7	