

**Oklahoma Department of Environmental Quality
Coal Combustion Residual (CCR) Disposal Facilities**

Western Farmers CCR Landfill	
Permit No.	Landfill: 3512008; Surface Impoundment: 3512008-SI (Closed 8/22/23)
Phone	(405)247-3351
Website Link	https://www.wfec.com/ccr-rule
Grand River Dam Authority CCR Landfill	
Permit No.	Landfill: 3549012
Phone	(918)824-7544
Website Link	https://grda.com/resources/ccr-rule-compliance-data/
Big Fork Ranch CCR Landfill	
Permit No.	Landfill: 3552014
Phone	(580)765-6693
Website Link	https://www.evansandassociatesconstructioncompany.com/
AEP - PSO NE Power Station CCR Landfill and Surface Impoundment	
Permit No.	Landfill: 3566010; Surface Impoundment: 3566010-SI
Phone	(918)581-0448
Website Link	https://www.aep.com/environment/ccr/Northeastern
OG&E Muskogee Power Station Surface Impoundment	
Permit No.	Surface Impoundment: Closed 3/2020
Phone	(405)553-3280
Website Link	https://www.ogeenergy.com/coal-combustion/