



RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Community Action Agency of Oklahoma City - Dana Brown Cooper HeadStart on October 27, 2023. Overall, sixteen (16) outlets were tested resulting in a total of thirty-two (32) samples being sent to the lab.

- Twenty-six (26) samples had no detectable level of lead.
- Six (6) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Description	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-TL-IM	Ice machine in Teachers' Lounge	<1.0	<1.0	N/A
1-1-TL-KF	Kitchen faucet in Teachers' Lounge	<1.0	<1.0	N/A
1-1-A-BF1	Bathroom faucet in Room A bathroom; right side	<1.0	<1.0	N/A
1-1-A-BF2	Bathroom faucet in Room A bathroom; left side	<1.0	<1.0	N/A
1-1-A-CF	Classroom faucet in Room A	<1.0	<1.0	N/A
1-1-KIT-KF2	Kitchen faucet on sink to left of door in kitchen	<1.0	<1.0	N/A
1-1-HALL -WC2	Elkay water cooler near kitchen and front entrance	<1.0	<1.0	N/A
1-1-C-CF	Classroom faucet in Room C	<1.0	<1.0	N/A
1-1-BC-BF1	Bathroom faucet in bathroom between Rooms B and C; right side	<1.0	<1.0	N/A
1-1-BC-BF2	Bathroom faucet in bathroom between Rooms B and C; left side	<1.0	<1.0	N/A
1-1-B-CF	Classroom faucet in Room B	<1.0	<1.0	N/A

Sample ID	Description	First Draw ($\mu\text{g/L}$)	Flush ($\mu\text{g/L}$)	Remedial Action
		Initial Sampling		
Low Detection (1.0 - 14.9 $\mu\text{g/L}$)				
1-1-KIT-KF1	Kitchen faucet on sink to right of door in kitchen	1.1	<1.0	
1-1-KIT -KF3	Kitchen faucet on three-compartment sink in kitchen	1.1	<1.0	
1-1-HALL -WC3	Elkay water cooler in back hallway near Rooms B and C	2.4	1.9	
1-1-OUT-DW	Drinking water spigot on playground	2.5	<1.0	
1-1-HALL -WC1	Elkay water cooler; Hall outside of teachers' lounge close to front entrance	5.9	<1.0	