

Attachment 3

RCRA Part B Permit Application

Security and Fencing

US Ecology Tulsa, Inc.

EPA ID: OKD000402396



Tulsa, Oklahoma

Permit Application

July 11, 2022

Attachment 3- Security and Fencing Table of Contents

1. Access Control.....	iii-1
2. Security Equipment.....	iii-1
3. Fencing Barrier Details.....	iii-1
4. Warning Signs.....	iii-1
5. Inspections of Security Equipment and Fencing.....	iii-2

Security Measures at US Ecology Tulsa, Inc.

1) Access Control

The US Ecology Tulsa, Inc. facility is surrounded by a fence and (where necessary) a flood control concrete wall. Access is restricted by monitored gates that must be open by employees in the main office. Visitors entering the facility are required to call the main office phone and identify themselves. They are then directed to the main office to sign in. Visitors are then escorted by a facility employee when in operating areas of the site. The main gate at the end of 25th West Avenue is the main entrance for truck traffic in and out of the facility. The south and west gates are available for egress as needed. All gates will be identified on the facility map provided in Attachment 1- Maps and figures.

2) Security Equipment

In addition to access-controlled fencing, US Ecology Tulsa, Inc. also has an alarm system on the office building (and fencing) that is monitored 24/7 by an outside company. The facility also has a camera system installed. Access to the facility is controlled by key fobs that are distributed to employees. A key fob is needed to access the facility entrance gate and the office building.

3) Fencing Barrier Details

US Ecology Tulsa, Inc. is surrounded by a 6-foot chain link fence with 3 strands of barbed wire posted at the top at a 45-degree angle. Location of fencing and access gates will be identified on the facility map in Attachment 1-Maps and Figures. Access control to gates is active 24/7.

4) Warning Signs

Warning signs are posted at each entrance to the active portion of the facility and along the fence exterior in sufficient number to be seen from any approach to the active portion. The signs are printed in English and are legible from a distance of at least 25ft. The signs posted read “Danger-Unauthorized Personnel Keep Out” in accordance with 40 CFR 264.14(c).

5) Inspections of Security Equipment and Fencing

US Ecology Tulsa, Inc. inspects security equipment and fencing on a weekly basis. Items inspected are provided in Attachment 4- Inspection Schedules and Forms.

-----End of Attachment-----