

**Former ArvinMeritor Site (Gabriel Ride Control)**

September 6, 2016

**Location:** 700 N. Industrial Blvd in Chickasha, Grady County, Oklahoma

**Background:** Manufactured shocks and struts from the early 1970s until 2006, when the facility switched to manufacturing only the steel rods for shock absorbers. There are other buildings on-site historically used for maintenance, paint drum storage, scrap metal storage, and classrooms.

**Air:** No know problems.

**Soil:** No known soil contamination under DEQ's jurisdiction. Some USTs and ASTs were closed out by the Corporation Commission (OCC). Any remaining soil contamination associated with the former tanks was not evaluated.

**Surface Water:** No surface water within the vicinity

**Groundwater:** LNAPL contamination is detected in two wells (MW-02 and MW-03). Plume is stable and limited.

**Private/Public Wells:** Only monitoring wells within the vicinity.

**Vapor Intrusion to Indoor Air:** None indicated.

**Key Questions:**

- **Have all known groundwater contaminant plumes been adequately evaluated and delineated?** Yes
- **Has the site been sampled for an adequate list of analytes?** Yes
- **Does soil or waste need to be cleaned up?** No
- **Has the surface water been sampled?** Not needed
- **Has soil at the site been cleaned up to levels protective of groundwater?** OCC did soil clean up associated UST/AST removals.