

Rexam Beverage Can Company

Location: The Site is located at 3400 South Council Road in Oklahoma City.

Background: The site had been used for the manufacture of two-piece aluminum beverage cans from 1978 to 2009.

Air: No known air quality issues.

Soil: Soils onsite have been investigated and a soil removal action was conducted for impacted soils. Based on the results of post-excavation soil sampling, all accessible impacted soil has been removed.

Surface Water: No surface water in the immediate vicinity

Groundwater: Groundwater on-site exists in two zones; a discontinuous, perched water table within unconsolidated deposits and a shallow, weathered bedrock zone.

Private/Public Wells: No wells have been identified

Vapor Intrusion to Indoor Air: No vapor intrusion issues are indicated.

Key Questions:

- **Have all known groundwater contaminant plumes been adequately evaluated and delineated?** Currently being characterized
- **Has the site been sampled for an adequate list of analytes?** Yes
- **Does soil or waste need to be cleaned up?** No
- **Has the surface water been sampled?** No surface water in the vicinity
- **Has soil at the site been cleaned up to levels protective of groundwater?** Yes. Soils have been investigated, and a soil removal action has taken place to remove impacted soils onsite.