



OKLAHOMA DRINKING WATER
LEAD TESTING
 IN PUBLIC SCHOOLS & CHILD CARE FACILITIES

District: Community Action Agency of OKC
 School: Kiddie Village HeadStart
 Sampling Date: 4/4/2024
 Status: Remediation

RESULTS

Below are the results from the first round of testing of drinking water for lead that was conducted at Community Action Agency of OKC - Kiddie Village HeadStart on April 4, 2024. Overall, eleven (11) outlets were tested resulting in a total of twenty-two (22) samples being sent to the lab.

- Twenty-one (21) samples had no detectable level of lead.
- One (1) samples had a low detection of lead between 1.0 and 14.9 µg/L.
- Zero (0) samples had a high detection of lead equal to or above 15.0 µg/L.

The table below shows all sample results. Sample results are in micrograms per liter, shown as µg/L. For more information on how to read this report, please see our **Results Interpretation Fact Sheet**.

Sample ID	Comments	First Draw (µg/L)	Flush (µg/L)	Remedial Action
		Initial Sampling		
Non-Detect (<1.0 µg/L)				
1-1-KIT-IM1	Ice machine to right of kitchen on first floor; under stairs	<1.0	<1.0	N/A
1-1-RR-BF1	Bathroom faucet in first floor boys' restroom; in middle of hall	<1.0	<1.0	N/A
1-1-RR-BF2	Bathroom faucet in first floor girls' restroom; under stairs at front of building	<1.0	<1.0	N/A
1-2-RR-BF1	Bathroom faucet in second floor boys' restroom; in middle of hall	<1.0	<1.0	N/A
1-2-RR-BF2	Bathroom faucet in second floor staff restroom; in office area	<1.0	<1.0	N/A
1-2-RR-BF3	Bathroom faucet in second floor girls' restroom; near back stairs	<1.0	<1.0	N/A
1-2-RR-BF4	Bathroom faucet in second floor staff restroom; near back stairs	<1.0	<1.0	N/A
1-3-HALL-WC1	Elkay water cooler on third floor; in middle of hall near boys' restroom	<1.0	<1.0	N/A
1-3-RR-BF1	Bathroom faucet in third floor boys' restroom; in middle of hall	<1.0	<1.0	N/A

Sample ID	Comments	First Draw ($\mu\text{g/L}$)	Flush ($\mu\text{g/L}$)	Remedial Action
		Initial Sampling		
1-3-RR-BF2	Bathroom faucet in third floor girls' restroom; near back stairs	<1.0	<1.0	N/A
Low Detection (1.0 - 14.9 $\mu\text{g/L}$)				
1-1-KIT-KF1	Kitchen faucet in three-compartment sink in kitchen	3.8	<1.0	